Dunouy's Surface Tension



Specification

Accessory	Qty.	No.	Accessory	Qty.
Aluminum base	1	2	Aluminum stand	1
Micro-adjustable stage	1	4	Movable system of surface	1
			tension measurement	
Dish	1	6	Ring	2
Mass	1pack	Pre-	Heater	1
		preparation		
Thermometer	1	Pre-	Liquid to be measured	1
		preparation		

All rights reserved